

4061 Repair kit Z90, 1/2", MATADOR item no.: 40610099



Beschreibung:
Repair kit for Z90 12.5 mm (1/2") 40610090.

4061

 Repair kit Z90, 1/2", MATADOR item no.: 40610099

Technische Daten

Manufacturer-Number:	4061 0099
EAN:	4040674237674
Width:	50 mm
Height:	30 mm
Length:	100 mm
Weight:	0.4 kg